

## XBA-MOP4 Option Switch Settings

Supported bill **BDC 10, 20, 50, 100**  
**BNU 10, 20, 50, 100 4bills.**


FUNCTION	SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8
★ Reject MOP 10 (Note 1)	ON							
★ Accept MOP 10 (Note 1)	OFF							
★ Reject MOP 20		ON						
★ Accept MOP 20		OFF						
★ Reject MOP 50			ON					
★ Accept MOP 50			OFF					
★ Reject MOP 100				ON				
★ Accept MOP 100				OFF				
★ Reserved					ON			
★ Reserved					OFF			
★ Disable Bill Reject 4 Times BA Stop By 30 Sec						ON		
★ Enable Bill Reject 4 Times BA Stop By 30 Sec						OFF		
★ Stack Banknote when Power-up							ON	
★ Reject Banknote when Power-up							OFF	
★ ENABLE IrDA Download								ON
★ Reserved								OFF

This dip switch is located at the side of XBA.

Note 1 : When Dip 1 is OFF ICT106U → MOP 10 = 0x40,  
MOP 20 = 0x41,  
MOP 50 = 0x42,  
MOP 100 = 0x43  
When Dip 1 is ON ICT106U → MOP 20 = 0x40,  
MOP 50 = 0x41,  
MOP 100 = 0x42

### Currency Assign Data


Interface	ICT106U		ccNet	ICT104V	Pulse	MDB
Bill value	When Dip 1 is OFF	When Dip 1 is ON				
BV1	10=0x40	20=0x40	10	10	10	10
BV2	20=0x41	50=0x41	20	20	20	20
BV3	50=0x42	100=0x42	50	50	50	50
BV4	100=0x43		100	100	100	100



## XBA-MOP4 (Pulse/MDB/ICT/ccNet)

FUNCTION		SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8
★	Inhibit Active HIGH	ON							
	Inhibit Active LOW	OFF							
★	Reserved		ON						
	Reserved		OFF						
★	Reserved			ON					
	Reserved			OFF					
★	Reserved				ON				
	Reserved				OFF				
★	Pulse Mode	MDB Mode		ccNet Mode					
	Credit-Pulse Normal HIGH	SCALING_FACTOR 100 DECIMAL_PLACE_OFF 2		9600 Baud Rate					
★	Credit-Pulse Normal LOW	SCALING_FACTOR 1 DECIMAL_PLACE_OFF 0		19200 Baud Rate		OFF			
	Pulse Mode								
★	Other Mode						OFF		
★	Pulse Mode		Other Mode						
	1 pulse / MOP 10		MDB Mode					OFF	OFF
	5 pulse / MOP 10		ICT106U Mode					OFF	ON
	10 pulse / MOP 10		ccNet Mode					ON	OFF
	20 pulse / MOP 10		ICT104V Mode					ON	ON

This dip switch is located on the CPU board, remove the CPU board cover first.



★ Manufacture setting

Note : 1.After setting dip switch of the credit pulses,you should reset the bill acceptor again.  
2.No sleep function.  
3.Calibrate card.