

P77/P5 DIP SWITCHES SETTING: 1

Supported bill DKK 50(99, 05), 100(99, 02), 200(03), 500(97, 03), 1000(98, 04) 5bills.

		000(31, 03), 10				000 (30, 0 1)			O DIII 3		
	FUNCTION	SW1	SW2	SW3	SW4	SW5	SW6	SW7	SW8	SW9	SW10
*	1 Pulse / DKK 50	OFF	OFF	OFF							
	2 Pulse / DKK 50	OFF	OFF	ON							
	3 Pulse / DKK 50	OFF	ON	OFF							
	4 Pulse / DKK 50	OFF	ON	ON							
	5 Pulse / DKK 50	ON	OFF	OFF							
	10 Pulse / DKK 50	ON	OFF	ON							
	20 Pulse / DKK 50	ON	ON	OFF							
	100 Pulse / DKK 50	ON	ON	ON							
	Fast output Pulse Lo= 50ms Hi=100ms				ON						
*	Slow output Pulse Lo= 50ms Hi=300ms				OFF						
	Inhibit level Active Low					ON					
*	Inhibit level Active High					OFF					
*	Accept DKK 50						ON				
	Reject DKK 50						OFF				
*	Accept DKK 100							ON			
	Reject DKK 100							OFF			
*	Accept DKK 200								ON		
	Reject DKK 200								OFF		
*	Accept DKK 500									ON	
	Reject DKK 500									OFF	
*	Accept DKK 1000										ON
	Reject DKK 1000										OFF

★ Manufacture setting

Note: (1)Please reset the bill acceptor after set the dip switch.

(2)Dip switches 1 to 5 are only used for pulse protocol.

DIP SWITCHES SETTING: 2

	FUNCTION	SW1	SW2	SW3	SW4
-	Pulse Normal High	ON			
	Pulse Normal Low				
	Pulse Protocol		ON		
	ICT Protocol		OFF		
Ī	HOLD			ON	
	HOLD			OFF	
	Ignore Sensor Problem(Note 1)				ON
-	Acknowledge Sensor Problem (Note 2)				OFF

★ Manufacture setting

Note: (1) Sensor 6 problem occurred ==>> BA will be still in working order.

(The face LED will be flashing in short green about 2 seconds everytime you restart BA.)

(2) BA will stop to work when it acknowledges Sensor 6 problem occurred. (The face LED will be flashing in red.)